



CLOSE OPEN

CLS 1-2		
CLS 1-3		
OLS 1-2		
OLS 1-3		
CTS 1-3	* CLOSING TORQUE SWITCH INTERRUPTS CONTROL IF MECHANICAL OVERLOAD OCCURS DURING CLOSING CYCLE	
OTS 1-3	* OPENING TORQUE SWITCH INTERRUPTS CONTROL IF MECHANICAL OVERLOAD OCCURS DURING OPENING CYCLE	

- CLS : CLOSE LIMIT SWITCH (250VAC 6A)
 - OLS : OPEN LIMIT SWITCH (250VAC 6A)
 - CTS : CLOSE TORQUE SWITCH (250VAC 6A)
 - OTS : OPEN TORQUE SWITCH (250VAC 6A)
 - TP : THERMAL PROTECTOR (250VAC 15A)
- *EACH ACTUATOR SHOULD BE POWERED THROUGH ITS OWN INDIVIDUAL SWITCH OR RELAY CONTACTS TO PREVENT CROSS FEED BETWEEN TWO OR MORE ACTUATORS

ABZ 15 THRU 28 (24 VDC) WIRING DIAGRAM		
SCALE	APPROVED BY:	DRAWN BY: EC
DATE: 6/20/00	REVIEWED:	
ABZ VALVES & CONTROLS		
113 W MAIN, MADISON, KS 66860		
DRAWING NUMBER: 16069DRS	REV:	-